

## Under Review Notification

Raised By: Steven Drouin

Product #: APICAL 135-21 CCK

Date: 17.08.02

Product Name: CABLE CUTTER INSTALLATION

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
647.7304	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7324	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7305	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7325	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7306	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7326	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7307	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7327	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7305	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7325	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7308	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.
647.7328	647.7300 REV C	Y	Y	Y	N	Y	Y	Y	17-611	647.1404 is missing from BOM.

**Description of Issue:**

647.7301,7302,7303 ARE OK TO SHIP

**Distribution:**

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider